

State of Ohio
Continuation Report

Authority: Chapters 3717 and 3715 Ohio Revised Code


4-5-18

Facility name White Springs Golf Club	Type of inspection Standard
--	--------------------------------

Violation(s)/Comment(s)

Address: 3630 St. Rt. 571 W. Greenville C35
license holder: Dean Foreman
license #: 1185

- (5.1J) observed a clear pipe creating a direct connection between ice machine & plumbing system. Discussed a plumbing system shall be installed to preclude backflow of a solid, liquid, or gas contaminant into the water supply system. Please remove clear pipe or submit spec sheet on ice machine to show if a backflow is built in. Please call when removed or submit spec sheet prior to use of machine.
- Discussed to contact Health Dept. for equipment approval or changes to the facility you are wanting to make, prior to making changes. 937-548-4194
- License issued.

Inspected by Megan Kellow	R.S./SIT # 143134	Licenser Darke Co #11
Received by 	Title GM	Phone 937-548-6546