Public Swimming Pool Inspection Report						Health District: / ALA COUNTY					
Name of Facility NUM VIIIAG	1117/	Type/vjšit	Type pool	Setti	ng	7. 7.		Specia	l feature (SF)		
Address/ DODI Drive City Arcanom			☐ Sandard☐ Re-inspection☐ Complaint☐ Epi Investigati☐ Consultation☐	I Pool □ SPA □ SUP	☑ Wading pool ☐ School ☐ Indoor ☐ Apartment/C ☐ Other		☐ Govt ☐ MHP ☐ Govt ☐ Camp ☐ Gondo ☐ Hotel/motel		☐ Kiddie slide ☐ Playground slide ☐ Rec slide ☐ Water slide ☐ Fountain ☐ Other		
Insp date (mm/dd/yy)///////////////////////////////			avel Time	ID no.	ID no.			License no.			
Surface area (sf)	Required turno rate (min) [ie 30		120	Volume (gall	ons)	26		Required flow min: (gpm) [Volume/TRate]		33	
☐ Check if in violation of the Ohio Administrative Code 3701-31-04 (A-E); NA= Not Applicable											
Flow measure	low:		Max allow. flo	Max allow. flow: SF pump capacity (gpm)			Max allow. flow: Je pump capacity (gp				
Critical violations (3701-31-04(B)(1)(a-l)	,	•									
(a) Outlet covers installed/secured/ in compliance	(d) Circulation/Disinfection system operating properly			(g) Water (can see p		ttom)		[] (j) Pool treated after RWI			
(b) SVRS devices functioning	(e) Automat	c chemical controller properly		(h) Natura	(h) Natural or artificial light			(k) Proper use/storage of chemicals			
(c) Disinfection residual as required	(c) Disinfection residual as required (f) Lifeguards			[](i) Fecal a	(i) Fecal accident treated pro			[] (I) No Electrical hazards present			
Water Quality 3701-31-04 C, D											
(Circle disinfectant used)			6) Total Chlorine- C	l ₂ (ppm)	om) A.		(C)(2) pH [7.2-7.8]			7.4	
Calcium Hypochlorite Sodium Hypochlorite Bromine Di-Chlor Tri-Chlor Salt **Monopersulfate (if present will interfere with DPD test kit results)		☐ (D)(6) Free Chlorine-Cl ₂	, (ppm) [≥1;2]	≥1;2]		(C)(3) Alkalinity (ppm) [min 60]			400	
		☐ (D)(6) Combined-Cl ₂ / (ppm) [≤ 1]	()		[(C)(6) Pool water temp [≤ 90° F]		***	79	
-Secondary disinfection (circle if used)			6)Total Bromine-Br	, (ppm) [≥2;4]			(C)(7) Spa water temp [≤ 104°F]				
ÜV light (MJoules/cm²) Özone (ppm)			6) ORP/HRR (millivo	olts) [<u>></u> 650]	[≥650]		(C)(8) Spa water replaced every 30 da		0 days		
lonization Conner Silver (nom)			5) Cyanuric acid (pp	om) <u><</u> 70		-					
Responsibilities of the Operator 3701-31-04					_				-		
(A) License is displayed or on file			(B)(7) No domestic animals unless otherwise permitted				(D)(9) Chemicals are manually added while bathers are not present				
(A) All construction or alterations of a pool done with approved plans			D)(1) No gas chlorine for disinfection				(E)(1) Exclusion of people with obvious infectious wound or experiencing diarrhea/vomiting				
☐ (B) All facilities are maintained clean, safe and sanitary condition and in good repair			(D)(2) Pool is continuously disinfected by a feeding device connected to circulation system				(E)(2) Safety equipment is visible and accessible				
(B)(2) Authorized representative available within 30 minutes			(D)(3) Mixing tank for spray ground has disinfection				(E)(3) Appropriate signs are posted				
☐ (B)(3) Staff are knowledgeable of equipment and pool operation			D)(4) Secondary dis offecting water qual	s not ac	dversely	(E)(4) Lifeguards are provided and on duty as required					
☐ (B)(4 & 5) Operational records maintained and on file			D)(7) Automatic choroperly	is functi	ioning		,				
☐ (B)(6) All equipment maintained in clean, safe and sanitary condition and in good repair			(D)(8) Test kit is maintained and complete								
THE ITEMS LISTED BELOW ARE IN VIOLATION OF OHIO ADMINISTRATIVE CODE CHAPTER 3701-31 AND MUST BE CORRECTED											
Cite the specific rule number, explain where ar	d what violation	has occi	urred, and when the	violation must b	e correc	cted.					
NO VIO	1000	7 <i>5</i>	notla	<i>Y</i> .							
REMARKS See additional remarks on the attached form, HEA	5217										
Re-inspection required? Yes No;											
Compliance date:) -)/(1-11101	100 A	A_{i}		}	T			
James narry Comers VI - P KUU	V Phon	MX	4140	Operator of R	presén //	tative		Phone	167-	1868	